

OVERFLOW REPORT

BOARD MEMBERS Gary Bechtel	DATE OF OVERFLOW: Friday, March 7, 2025, 3:30 pm – 10:30 pm
Chairman	REPORT SUBMITTED: Monday, March 10, 2025
Frank Patterson Vice-Chairman	LOCATION OF OVERFLOW: <u>1140 Oakcliff Road</u> – MH ID: 82722 (Please note that the address used is a reference for the location of the manhole.)
Elaine H. Lucas	
Desmond Brown	CALLEE OF OVERFLOW: After clearing the blackage, we determined that the miner
Dwight Jones Bill Howell	CAUSE OF OVERFLOW: After clearing the blockage, we determined that the minor overflow was caused by debris in the sewer main.
Valerie Wynn	ESTIMATED VOLUME DISCHARGED: 8,400 gallons (Please note that this quantity is only a calculated estimation of the volume of sewage
Ron Shipman Executive Director	that spilled from our system. More sewage may have escaped the system.)
& President	SERVICE BASIN AFFECTED: Main Street
790 Second Street	CORRECTIVE ACTION TAKEN TO MITIGATE OR TO REDUCE ADVERSE EFFECTS: The blockage has been cleared, and debris has been removed. This area has also been sprayed with an enzyme treatment for organic waste called Bio-bug.
P.0.Box 108	sprayed with an enzyme treatment for organic waste called blo-bug.
Macon, GA 31202 (478) 464-5600	OVERFLOW STATUS: The blockage has been removed; sewage is no longer escaping.
Fax: (478) 750-2007 MaconWater.org	SIGNS POSTED: Saturday, March 8, 2025
, i i i i i i i i i i i i i i i i i i i	CORRECTIVE ACTION TAKEN TO PREVENT FUTURE OVERFLOW: This line is scheduled for cleaning and CCTV inspection. It will also be added to the Hotspot Inspection list for ongoing monitoring.

MEDIA / HEALTH DEPARTMENT / OTHERS NOTIFIED: Macon Telegraph and Macon-Bibb County Health Department

REPORT SUBMITTED BY: Bryan Jones