

## **OVERFLOW REPORT**

BOARD MEMBERS	DATE OF OVERFLOW: Tuesday, January 28, 2025, 2:20 pm – 5:00 pm
Gary Bechtel Chairman	REPORT SUBMITTED: Thursday, January 30, 2025
Frank Patterson Vice-Chairman	<b>LOCATION OF OVERFLOW:</b> <u>3824 Thompson Road</u> – MH ID: 61964 (Please note that the address used is a reference for the location of the manhole.)
Elaine H. Lucas	
Desmond Brown	<b>CAUSE OF OVERFLOW:</b> After clearing the blockage, we determined that the minor overflow was caused by grease in the sewer main. No commercial sources of grease
Dwight Jones	
Bill Howell	have been identified upstream from this location.
Valerie Wynn	
Ron Shipman Executive Director & President	<b>ESTIMATED VOLUME DISCHARGED:</b> 3,200 gallons (Please note that this quantity is only a calculated <b>estimation</b> of the volume of sewage that spilled from our system. More sewage may have escaped the system.)
	SERVICE BASIN AFFECTED: Wolf Creek
790 Second Street	<b>CORRECTIVE ACTION TAKEN TO MITIGATE OR TO REDUCE ADVERSE EFFECTS:</b> The blockage has been cleared, and debris has been removed. This area has also been
P.0.Box 108	sprayed with an enzyme treatment for organic waste called Bio-bug.
Macon, GA 31202	
(478) 464-5600 Fax: (478) 750-2007	OVERFLOW STATUS: Sewage is no longer escaping.
MaconWater.org	SIGNS POSTED: Tuesday, January 28, 2025
	CORRECTIVE ACTION TAKEN TO PREVENT FUTURE OVERFLOW: This line is

scheduled for cleaning and CCTV inspection. It will also be included in the Hotspot Inspection list for ongoing monitoring. Additionally, the details of this overflow have been forwarded to our Grease Management team for further investigation.

**MEDIA / HEALTH DEPARTMENT / OTHERS NOTIFIED:** Macon Telegraph and Macon-Bibb County Health Department

**REPORT SUBMITTED BY:** Bryan Jones