

OVERFLOW REPORT

BOARD MEMBERS
Gary Bechtel
Chairman
Frank Patterson
Vice-Chairman
Elaine Lucas
Desmond Brown
Dwight Jones
Bill Howell

Ron Shipman
Executive Director
& President

Valerie Wynn

790 Second Street

P.O.Box 108 Macon, GA 31202 (478) 464-5600 Fax: (478) 750-2007 **MaconWater.org** DATE OF OVERFLOW: Monday, December 9, 2024, 5:00 pm - 8:00 pm

REPORT SUBMITTED: Tuesday, December 10, 2024

LOCATION OF OVERFLOW: <u>3941 River Place Drive</u> – MH ID: 65058 (Please note that the address used is a reference for the location of the manhole.)

CAUSE OF OVERFLOW: After the blockage was removed, it was determined that the cause of this minor overflow was due to grease. There are commercial sources of grease upstream from this location.

ESTIMATED VOLUME DISCHARGED: 2,160 gallons

(Please note that this quantity is only a calculated **estimation** of the volume of sewage that spilled from our system. More sewage may have escaped the system.)

SERVICE BASIN AFFECTED: Beaverdam Creek

CORRECTIVE ACTION TAKEN TO MITIGATE OR TO REDUCE ADVERSE EFFECTS:

The blockage has been cleared and debris has been removed. This area has also been sprayed with an enzyme treatment for organic waste called Bio-bug.

OVERFLOW STATUS: Sewage is no longer escaping.

SIGNS POSTED: Tuesday, December 10, 2024

CORRECTIVE ACTION TAKEN TO PREVENT FUTURE OVERFLOW: This line is scheduled to be cleaned using grease emulsifier and televised. It has also been added to the Hotspot Inspection list for ongoing monitoring. The details of this spill have been forwarded to our Grease Management team for further investigation.

MEDIA / HEALTH DEPARTMENT / OTHERS NOTIFIED: Macon Telegraph and Macon-Bibb County Health Department

REPORT SUBMITTED BY: Bryan Jones