



OVERFLOW REPORT

BOARD MEMBERS

Gary Bechtel
Chairman

Frank Patterson
Vice-Chairman

Calder B. Clay III
Desmond Brown

Dwight Jones

Bill Howell

Valerie Wynn

Ron Shipman
Executive Director
& President

790 Second Street

P.O.Box 108
Macon, GA 31202
(478) 464-5600
Fax: (478) 750-2007

MaconWater.org

DATE OF OVERFLOW: Wednesday, October 2, 2024, 9:02 am – 9:53 am

REPORT SUBMITTED: Friday, October 4, 2024

LOCATION OF OVERFLOW: [4765 Riverside Drive](#) – MH ID: 65108
(Please note that the address used is a reference for the location of the manhole.)

CAUSE OF OVERFLOW: After the blockage was removed, it was determined that the cause of this minor overflow was grease. There are commercial sources of grease upstream from this location.

ESTIMATED VOLUME DISCHARGED: 2,295 gallons
*(Please note that this quantity is only a calculated **estimation** of the volume of sewage that spilled from our system. More sewage may have escaped the system.)*

SERVICE BASIN AFFECTED: Beaverdam Creek

CORRECTIVE ACTION TAKEN TO MITIGATE OR TO REDUCE ADVERSE EFFECTS:
The blockage has been cleared and debris has been removed. This area has also been sprayed with an enzyme treatment for organic waste called Bio-bug.

OVERFLOW STATUS: Sewage is no longer escaping.

SIGNS POSTED: October 2, 2024

CORRECTIVE ACTION TAKEN TO PREVENT FUTURE OVERFLOW: The details of this minor overflow have been forwarded to our Grease Management team for further investigation. This line is scheduled to be cleaned with grease emulsifier and televised. We will continue to monitor the location on our Hotspot Inspection list.

MEDIA / HEALTH DEPARTMENT / OTHERS NOTIFIED: Macon Telegraph and Macon-Bibb County Health Department

REPORT SUBMITTED BY: Bryan Jones